Informal document No. **21** (32 GRSP, 10-13 December 2002, agenda item B.2.)

Amendments to document DOC TRANS/WP29/GRSP/2001/16/Rev.2 CLEPA proposal

§ 6.3.3.2.2. No-Slack indicator

The ISOFIX top tether strap or the ISOFIX child seat shall be equipped with a device that will indicate that any slack has been removed from the strap. The device may be part of adjustment and tension relieving device.